HARE COULTE

DELAWARE COUNTY HEALTH DEPARTMENT

100 WEST MAIN STREET, ROOM 207 MUNCIE, INDIANA 47305 OFFICE (765)747-7721 FAX (765)747-7747

SWIMMING POOL - INSPECTION REPORT

	ON / ADDRESS OF POOL Silvertree In. Mino	ie, in 4/3.	
TAI	RIAN: Christiana Mann		DATE: 05-27-2010
Ar	n inspection of your swimming pool has been made marked with		I you are directed to correct conditions
	Pool Structure:	F.	Showers, Toilets, Dressing Rooms
	Floors, Walls, Runways ()		Clean, Adequate, Access ()
	2. Scum gutters, Skimmers ()		2. Ventilation ()
	3. Ladders, Stairs, Stepholes ()		3. Hot, Cold water ()
	4. Diving boards, Float, Depth ()		4. Soap, Towels ()
	5. Inlets, Outlets, Circulation ()		5. Disinfection ()
	6. Piping ()		6. Lavatories ()
	7. Fencing ()		7. Clothing Storage ()
	8. Other ()		8. Refuse Containers ()
			9. Other ()
B.	Supplemental Facilities:		
	1. Food Service	G.	Records
	2. Emergency Equipment ()		1. Number of Bathers
	3. Other ()		2. Temp-water 78 (F) ()
	3. Other ()		Operational Data ()
	Recirculation, Disinfection System		4. Other ()
	1. Filtration, Disinfection ()		
		H.	Bather Control
	2. Other ()		Cleansing Shower ()
	Buildings, Galleries, Enclosures		Communicable Disease ()
).	Walls, Floors, Ceilings, Part ()		4. Placards Displayed
	2. Lights, Heating, Ventilation ()		5. Common Comb, Towel
	3. Plumbing, Drainage ()		6. Rented Suits and Towels
			Properly Handled and Clean
	4. Surroundings ()		7. Other ()
	5. Appurtenances ()		
	6. Other ()	1.	Hot Tub / Spa
	Weter	**	1. Disinfect Levelppm/ff()
	1. Disinfect Levelppm 7(2)		2. pH
			3. Other
	2. Freedom From Turbidity,		4. Other ()
	Debris, Growths ()		5. Other ()
	3. pH()		6. Other ()
	4. Other ()		0. Odlo
ark			-1 -1 10
4	A TO OVERATE OU	IN,	WATER SHAPE
	EUF /		,
1	100	11	/